

Installation guide

To view our complete installation video, scan the below QRcode or visit: www.havells-sylvania.com/led/lumiance/inverto/video



Mark-out and drill holes.




Add gasket.



Bring cables through glands, strip back and screw base moulding to mounting box.



Add Vidalfox sleeving, clamp power-in cable and wire-in to terminal blocks.



Repeat step 4/ for linking cable.



Choose between high efficiency and high output settings.



Fit head to base and tighten screws to seal.



Add any accessories.



Snap bezel onto the fitting.