



## Tech note

From Danfoss Residential Heating – PL61

Date: 2019-03-19

### Danfoss Eco™

#### Description

Please notice that 1<sup>st</sup> March the software 2.08 was released in production. When ordering from CDC you will then soon receive Eco™ with this new SW version. As the new SW contains production improvements, and only very minor bug fixes, we will not release the version to Danfoss Eco™'s that is already installed in the field – **no Software Over the Air update**- Once there is a planned update to those, we will merge the SW versions before release.

Version	Date	Improvements
2.08*	01-03-2019	<ul style="list-style-type: none"><li>• E9 will no longer be displayed</li><li>• Production improvements</li><li>• Minor bug fixes</li></ul> <p><i>*Please notice that 1st March 2019 the software 2.08 was released in production. This software is not available over the air update.</i></p>

#### Relevant code no B2B

014G1000, 014G1001, 014G1002, 014G1003, 014G1004, 014G1020, 014G1021

#### Relevant code no B2C

014G1100, 014G1101, 014G1102, 014G1103, 014G1104, 014G1105, 014G1106, 014G1107, 014G1108, 014G1109, 014G1110, 014G1111, 014G1112

#### Literature

Software overview document for Danfoss Eco™ will be updated ASAP.

#### Technical support

Alex Holm

Danfoss A/S,  
Ulvehavevej 61  
7100 Vejle

Phone: +45 5133 9795

E-mail: [alex.holm@danfoss.com](mailto:alex.holm@danfoss.com)