




## INSTRUCTIONS

AKS 11  
Pt 1000 ohm

084R9690



| ohm | °C  | °F  |
|-----|-----|-----|
| 803 | -50 | -58 |
| 807 | -49 | -56 |
| 811 | -48 | -54 |
| 815 | -47 | -53 |
| 819 | -46 | -51 |
| 823 | -45 | -49 |
| 827 | -44 | -47 |
| 831 | -43 | -45 |
| 835 | -42 | -44 |
| 839 | -41 | -42 |
| 843 | -40 | -40 |
| 847 | -39 | -38 |
| 851 | -38 | -36 |
| 855 | -37 | -35 |
| 859 | -36 | -33 |
| 862 | -35 | -31 |
| 866 | -34 | -29 |
| 870 | -33 | -27 |
| 874 | -32 | -26 |
| 878 | -31 | -24 |
| 882 | -30 | -22 |
| 886 | -29 | -20 |
| 890 | -28 | -18 |
| 894 | -27 | -17 |
| 898 | -26 | -15 |
| 902 | -25 | -13 |
| 906 | -24 | -11 |
| 910 | -23 | -9  |
| 914 | -22 | -8  |

| ohm  | °C  | °F |
|------|-----|----|
| 918  | -21 | -6 |
| 922  | -20 | -4 |
| 926  | -19 | -2 |
| 929  | -18 | 0  |
| 933  | -17 | 1  |
| 937  | -16 | 3  |
| 941  | -15 | 5  |
| 945  | -14 | 7  |
| 949  | -13 | 9  |
| 953  | -12 | 10 |
| 957  | -11 | 12 |
| 961  | -10 | 14 |
| 965  | -9  | 16 |
| 969  | -8  | 18 |
| 973  | -7  | 19 |
| 977  | -6  | 21 |
| 980  | -5  | 23 |
| 984  | -4  | 25 |
| 988  | -3  | 27 |
| 992  | -2  | 28 |
| 996  | -1  | 30 |
| 1000 | 0   | 32 |
| 1004 | 1   | 34 |
| 1008 | 2   | 36 |
| 1012 | 3   | 37 |
| 1016 | 4   | 39 |
| 1020 | 5   | 41 |
| 1023 | 6   | 43 |
| 1027 | 7   | 45 |

| ohm  | °C | °F |
|------|----|----|
| 1031 | 8  | 46 |
| 1035 | 9  | 48 |
| 1039 | 10 | 50 |
| 1043 | 11 | 52 |
| 1047 | 12 | 54 |
| 1051 | 13 | 55 |
| 1055 | 14 | 57 |
| 1058 | 15 | 59 |
| 1062 | 16 | 61 |
| 1066 | 17 | 63 |
| 1070 | 18 | 64 |
| 1074 | 19 | 66 |
| 1078 | 20 | 68 |
| 1082 | 21 | 70 |
| 1086 | 22 | 72 |
| 1090 | 23 | 73 |
| 1093 | 24 | 75 |
| 1097 | 25 | 77 |
| 1101 | 26 | 79 |
| 1105 | 27 | 81 |
| 1109 | 28 | 82 |
| 1113 | 29 | 84 |
| 1117 | 30 | 86 |
| 1121 | 31 | 88 |
| 1124 | 32 | 90 |
| 1128 | 33 | 91 |
| 1132 | 34 | 93 |
| 1136 | 35 | 95 |

Approx. 4 ohm/°C Approx. 2.25 ohm/°F

