



FlexScan & FlexTester Test Port Adapters

Features:

- Tool-free, switchable connector adapters
- Available for most fiber connector types

Applications:

- FlexScan (FS200) & FlexTester (FLX380, OFL280) OTDR/OLS port adapters
- FlexScan & FlexTester OPM port adapters
- FlexScan & FlexTester VFL port adapters

Product Description

FlexScan® & FlexTester Test Port Adapters

Test ports on FlexScan (FS200) and FlexTester (FLX380, OFL280) handheld OTDRs are equipped with tool-free switchable adapters, which can be changed in seconds. The fast change switchable adapters allow OTDR, Optical Light Source (OLS), Optical Power Meter (OPM) and Visual Fault Locator (VFL) ports to connect to launch cables and jumpers having a variety of connector styles.

Select from the following adapters for the OTDR/OLS, OPM, and VFL ports on the FlexScan (FS200) and FlexTester (FLX380, OFL280) OTDRs:

OTDR Port Adapters

Part Number	Type
2900-50-0002MR	FC
2900-50-0003MR	SC
2900-50-0004MR	ST
2900-50-0006MR	LC
8500-10-0007	Bare Fiber Adapter

OPM Port Adapters

Part Number	Type
2900-52-0001MR	FC
2900-52-0002MR	SC
2900-52-0003MR	ST®
2900-52-0004MR	LC
2900-52-0005MR	2.5 mm Universal
2900-52-0006MR	1.25 mm Universal

VFL Test Port Connector Adapters

Part Number	Type
2900-53-0001MR	2.5 mm Universal
2900-53-0002MR	1.25 mm Universal